

Approved For Release 2009/03/05: CIA-RDP85T00339R000400050002-5

25X1

N-8279 NPIC (2/73)

SECRET

(c) NATIONAL PHOTOGRAPHIC INTERPRETATION CENTER

\sim	_	11	4
٠,	-	x	7
_		$^{\prime}$	- 1

Attachment to N-8279/73 6 February 1973 Page 1 of 2 COPY

REFERENCE TO: GS-680

REPAIR ACTIVITY
DONG HOI AIRFIELD
NORTH VIETNAM

1.	SIGNIFICANCE:	REPAIR TO THE SOUTHERNMOST AIRFIELD IN NORTH				
		VIETNAM FOLLOWING THE ANNOUNCED CEASE-FIRE AND				
	·	BOMBING HALT.				
2.	LOCATION:	DONG HOI AIRFIELD IS 2.9 NM NORTH-	5 X 1			
		NORTHEAST OF DONG HOI AT 17-30-38N 106-35-46E.				
3.	BACKGROUND:	DONG HOI AIRFIELD HAS NOT BEEN FULLY SERVICEABLE				
ř		SINCE BUT WAS LAST PARTIALLY RESTORED 2	5 X 1			
		IN THE AIRFIELD WAS STRUCK AFTER 2	5X1			
		AND HAS BEEN INACTIVE SINCE. THE LAST AOB AT	5X1			
		DONG HOI WAS ONE MIG-21 BETWEEN 2	5 X 1			
		THE AIRFIELD CONTAINS A SINGLE PACKED EARTH RUNWAY				
		25	X1			
4.	FIRST IDENTIFICATION:	LATEST REPAIR ACTIVITY - THIS MISSION.				

WARNING NOTICE ensitive Intelligence Sources and Methods Involved.

These notes have been prepared for briefing purposes only and should not be used for detailed analytical work. Their use should be restricted to the particular briefing boards (s) they were prepared for and must be considered valid only for the reporting period as indicated by the date of issue. For information concerning these notes contact Chief, Imagery Exploitation Group NPIC.

SECRET

25X1

25X1

Approved For Release 2009/03/05 : CIA-RDP85T00339R000400050002-5

SECRET

(c) NATIONAL PHOTOGRAPHIC INTERPRETATION CENTER

Attachment to N-8279/73 6 February 1973

Page 2 of 2

25X1

25X1

5. MISSION READOUT: PHOTOGRAPHY OF 22 JANUARY REVEALED REPAIR ACTIVITY AT DONG HOI AIRFIELD. FIVE CRATERS IN THE CENTER PORTION OF THE RUNWAY HAD BEEN REPAIRED AND TWO OTHERS WERE BEING FILLED BY BULLDOZER (FIGURE 1). PERSONNEL WERE OBSERVED APPARENTLY ENGAGED IN FINAL REPAIR WORK ON ANOTHER LARGE CRATER IN THE CENTRAL PORTION OF THE RUNWAY (FIGURE 2). SEVEN CRATERS REMAINED UNREPAIRED. NO RECONSTRUCTION OR REPAIR WAS APPARENT TO SUPPORT FACILITIES. CONSTRUCTION EQUIPMENT INCLUDED TWO BULLDOZERS (PROBABLE D-275) AND FIVE CARGO TRUCKS AND TWELVE PROBABLE HANDCARTS.

ENLARGEMENT

BASE PHOTO - 5X ENLARGEMENTS - 40X

IEG/SGD/SAB

These notes have been prepared for briefing purposes only and should not be used for detailed analytical work. Their use should be restricted to the particular briefing boards (s) they were prepared for and must be considered valid only for the reporting period as indicated by the date of issue. For information concerning these notes contact Chief, Imagery Exploitation Group NPIC.

SECRET

25X1

Approved For Release 2009/03/05 : CIA-RDP85T00339R000400050002-5

MARIE



NATIONAL PHOTOGRAPHIC INTERPRETATION CENTER


N-8279/73

NPIC CONTROL NUMBER





Stulet



25X1

25X1

25X1

25X1

25X1

25X1

25X1

Approved For Release 2009/03/05 : CIA-RDP85T00339R000400050002-5